



1. 197 Green Street, view southwest.



2. 197 Green Street, view southwest.



3. L-R: Enclosed porch, rear ell, enclosed porch, rear elevation of main block.



4. Southeast (facade) elevation.



5. Northeast elevation.



6. Bay window on northeast elevation.



7. Main entrance on southeast elevation.



8. Secondary entrance on southeast elevation.



9. Secondary entrance and enclosed porch on southeast elevation.



10. Enclosed porch on rear of building.



11. South half of rear ell and entrance from enclosed porch on rear.



12. Historic two-over-two wood sash window.



13. Main entrance and vestibule.



14. Main staircase.



15. Main staircase newel post.



16. Main staircase detail.



17. Front room and vestibule on first floor.



18. Front room on first floor.



19. Main staircase.



20. Hall on second floor.



21. Southwest bedroom on second floor.



22. Front bedroom on second floor.



23. Front bedroom on second floor.



24. Northwest bedroom on second floor.



25. North half of rear ell.



26. Rear staircase from second floor.



27. South half of rear ell with infilled entrance to remainder of the ell at center.